
"Trace & Repair of Commerical Gas Pipe Leak Under Car Park Ground at the Hotel"

(Photos include some parts of the process: Trace the Gas Leak, Pipe Purging, Replacement of Gas Pipes, Sefety Test, Re-Connection of Gas Supply Heating Sytem and all Appliances)

























"Safety Check and Service on Commercial Heating System"



"Replacement of Commercial Gas Flue on Commercial Buidling"





14 / 24





















